

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2025

Submitted Date:

03/24/2025

Document Number:

710500464

FIELD INSPECTION FORM

Loc ID 321117 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 61650
Name of Operator: MURFIN DRILLING COMPANY INC
Address: 250 N WATER ST STE 300
City: WICHITA State: KS Zip: 67202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Serna, Abe		abe.serna@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Goodrich, Christina		cgoodrich@murfininc.com	Murfin Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206084	WELL	TA	12/02/2011	OW	009-06500	S.E. CAMPO UNIT 605	EI
321117	LOCATION	AC			-	S.E. CAMPO UNIT-635S46W 1NENW	EI

General Comment:

[This is an Environmental Inspection for the S E CAMPO UNIT # 605, API # 05-009-06500 well location and Rem # 37143](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign at wellhead		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	At the time of inspection, unused equipment was observed on location.		
Corrective Action:	Comply with Rule 606		Date: <u>04/22/2025</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	At the time of inspection, stained soils observed running from the wellhead west off location coming to a stop in an area previously undisturbed by oil and gas activity		
Corrective Action:	Report spill or release of E&P waste or produced fluids, contact ECMC EPS staff per Rule 912.b.		Date: <u>03/25/2025</u>
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Temporary fencing installed at wellhead excavation		
Corrective Action:			Date:
Type	OTHER		
Comment:	Fencing around ancillary equipment		
Corrective Action:			Date:
Equipment:			
Type: Flow Line	# 1		corrective date
Comment:	At the time of inspection, a flowline riser observed at the wellhead. Comply with Rule 1105 for flowline decommissioning		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 206084 Type: WELL API Number: 009-06500 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 321117 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
Oily Soil	Piles	Inadequate	
Comment	At the time of inspection, spoil pile from wellhead excavation was stored on location on a tarp without berms. Evidence of soil migration from stormwater impacts were present Per Rule 913.b.(5).B.iv. Operators will properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.		
Corrective Action	Operator shall properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil in accordance with Rule 913.b.(5).B.iv.		Date: <u>04/08/2025</u>

Spill/Remediation:

Comment:	Remediation project # 37143 is ongoing. At the time of inspection, impacted soils observed within the wellhead excavation. Per Form 6s Document # 404039247, wellhead cut and capped date of 12/09/2024. Operator did not report Spill or Release discovered during facility closure operations in the wellhead excavation in accordance with Rule 913.f.. Operator shall provide all analytical data and information collected at the time the wellhead was cut and capped.		
Corrective Action:	Report spill or release of E&P waste or produced fluids, contact ECMC EPS staff per Rule 912.b.	Date: <u>03/25/2025</u>	

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
Wellhead cut and capped on 12/09/2024 per Form 6s Document # 404039247	sanchezcc	03/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500465	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6971650