

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2025

Submitted Date:

03/24/2025

Document Number:

717000317

FIELD INSPECTION FORMLoc ID 319973 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
EUGENE FRITZLER		gfritzler12@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202067	WELL	PR	06/01/2024	OW	001-07472	SIMPSON A 12	PR

General Comment:

Routine inspection / nochange to equipment

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:		<div>Adequate</div>		
Corrective Action:				Date: <div></div>
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:		<div></div>		
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: <div></div>
Flaring:				
Type				
Comment:				
Corrective Action:				Date: <div></div>

Inspected Facilities

Facility ID: 202067 Type: WELL API Number: 001-07472 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test:	12/11/2024	Annual Brhd Completed?	
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	NONE
	End Surf Csg Pressure: 0		
Comment:	Appeares to be plumbed to the surface		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine inspection	finkenbc	03/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000318	Inspection photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6972101