

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2025

Submitted Date:

03/24/2025

Document Number:

708906083**FIELD INSPECTION FORM**Loc ID 322314 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 3 GREENWAY PLAZA STE 1360City: HOUSTON State: TX Zip: 77046**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments
2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Mustang		nwelch@venatorresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210256	WELL	PR	07/01/2024	GW	045-06012	RULISON FEDERAL 35-94-6S-94W	PR

General Comment:**CECMC Inspection/Audit Report Summary**

On 03/17/2025 at approximately 15:07 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection/audit at MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad.

Location # 322314 in Garfield County Colorado.

Please refer to inspection/audit 708903514 conducted on 04/11/2024 & inspection/audit 708904967 conducted on 11/04/2024, previous corrective action has not been completed.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Location is approximately 272 yards from Porcupine Creek.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Housekeeping - Unused equipment on location with a CA date of 05/11/2024
2. Housekeeping - Dead weeds/debris on location with a CA date of 03/31/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/1-888-291-8588		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	<p>Unused equipment on location - extra meter house on location & equipment is not in use.</p> <p>Please refer to FORM 4 document # 403769842</p> <p>Operator stated "A meter house has been staged on location for installation of telemetry equipment. Mustang will complete the installation no later than October 31,2024 as instrumentation and electrical team is available."</p> <p>At the time of inspection meter house has not been hooked up/is unused equipment</p>		
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.		Date: 05/11/2024
Type	DEBRIS		
Comment:	Dead weeds/debris on location		
Corrective Action:	Comply with CECMC 600 series rules		Date: 03/31/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment:	1 meter house is not hooked up & not in use/unused equipment, please refer to Housekeeping for CA			
Corrective Action:			Date:	
Type: Plunger Lift	# 0			
Comment:	Well is not on plunger lift			
Corrective Action:			Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

--	--	--	--	--

Inspected Facilities									
Facility ID:	210256	Type:	WELL	API Number:	045-06012	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well is not on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
Gravel						Sparse to none in most areas
Compaction						Light compaction in some areas
		Gravel				
		Compaction				
Other						Rill erosion starting to develop near meter house

Comment: [Rill erosion starting to develop near meter house](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Housekeeping for corrective actions	smelserw	03/24/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906084	Inspection/Audit 708906083 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6972549
708906085	Inspection/Audit 708906083 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6972550