

Rhoades 22-35 #2
Attachment A - Photolog
(October 10, 2024)



Description: Stained soil located around the disconnected compressor



Description: Excavation of stained soil located around the disconnected compressor



Description: Excavation of stained soil located around the disconnected compressor



Description: Backfill located around the disconnected compressor



Description: Impacted soil was removed around the wellhead by hand.



Description: Backfill around the wellhead



Description: Stained soil was removed below pump by hand.



Description: Stained soil was removed below pump by hand.



Description: Backfill below pump



Description: Backfill below pump

