

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2025

Submitted Date:

03/18/2025

Document Number:

697602466

**FIELD INSPECTION FORM**Loc ID 445801 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>
Kiel, Macy		Macy_Kiel@oxy.com	<a href="#">Oxy Environmental</a>
Mickelson, Erik		Erik_Mickelson@oxy.com	<a href="#">Oxy Environmental</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446830	TANK BATTERY	AC	07/22/2016		-	CHIKUMA 1-13A&HARRY O SA 34002261	EI
488496	SPILL OR RELEASE	CL	11/11/2024		-	Chikuma 1-13A&Harry Facility	EI

**General Comment:**

ECMC Environmental Inspection to determine progress on the Chikuma 1-13A & Harry Facility (Spill ID 488496). Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	OTHER				
Comment:	Fencing around the excavation has fallen.				
Corrective Action:	Operators will fence or cover open trench/excavation to prevent access when sites are not attended Remediation Safety fence Rule 913.b.(5)B.			Date:	03/25/2025
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	446830	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	488496	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Comment	No waste at the site			
Corrective Action				Date:

**Spill/Remediation:**

Comment:	Excavations open as the remediation is under way			
Corrective Action:				Date: _____

Emission Control Burner (ECB):	_____			
Comment:				
Pilot:	_____	Wildlife Protection Devices (fired vessels):	_____	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404132398	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6964578">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6964578</a>
697602467	Photolog	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6964577">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6964577</a>