

Inspection Photos

Loc #: 487587

Operator: DESERT EAGLE OPERATING

Inspection Date: 3/24/2025

County: Las Animas



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. Topsoil was salvaged along the road.



Inspection Photos



Photo 2. Facing toward the topsoil pile salvaged along the road. The topsoil will need to be seeded for long term stabilization..



Inspection Photos



Photo 3. Facing south near the location. This portion of the road was very rocky and topsoil was not salvaged at this area.



Inspection Photos



Photo 4. Facing south at the location. Topsoil has been salvaged from the location.



Inspection Photos



Photo 5. The topsoil pile has been stored at the south side of the location and was tracked for temporary stabilization..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 487587 | Date: 3/24/2025

Inspection Photos



Photo 6. Facing northwest at the location. There were no stormwater BMP's installed at the location at the time of inspections. BMP's need to be installed prior to construction.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 487587 | Date: 3/24/2025