

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Deadman # & Marked	# 6			
Comment:				
Corrective Action:				Date:
Type: Progressive Cavity	# 1			
Comment:	TR WELL			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:				
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	TR WELL			
Corrective Action:				Date:
Type: Compressor	# 1			
Comment:	TR WELL			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	FRAC VALVE ON ORIGINAL WELLHEAD			
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:				Date:
Type: Vertical Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 2			
Comment:	BOTH ARE ACCESSABLE			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 276458 Type: WELL API Number: 071-08340 Status: PR Insp. Status: PR

Producing Well

Comment: WELL IS PRODUCING THROUGH FRAC VALVE, WELL IS SET IN PROCESS OF SETTING UP FOR FRAC.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/06/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 279986 Type: WELL API Number: 071-08534 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/06/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 281436 Lat: 37.229080 Long: -104.839421

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective

Date: _____

ECMC Comments

Comment	User	Date
TR PIT HAS BEEN RECLAIMED.	beardslt	03/26/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300739	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6975988