

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2025

Submitted Date:

03/27/2025

Document Number:

716300766**FIELD INSPECTION FORM**Loc ID 429883 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Tim		thart@fremontpetroleum.com	<a href="#">All inspections</a>
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@fremontpetroleum.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429882	WELL	SI	04/16/2020	OW	043-06219	Amerigo Vespucci 1	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	PHOTO 8 & 9: NFPA STICKER IS FADED AND NEEDS REPLACED, TANK CONTENTS AND CAPACITY LABEL IS NOT SUFFICIENT. (THE PRODUCED WATER TANK AND THE EASTERN MOST CRUDE OIL TANK).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	04/27/2025

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	WEEDS ON OR INSIDE BERMS SHOULD BE COMPLETELY REMOVED INCLUDING ROOT STRUCTURES.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	100 BBLs	STEEL AST			
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	SHARES BERMS WITH CRUDE OIL BATTERY					
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		38.333510,-105.179365	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	429882	Type:	WELL	API Number:	043-06219	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	WELL IS PRODUCING AT TIME OF INSPECTION LAST PRODUCTION RECORD ON FILE 1/1/2025. NOTE: GAS METER IS LOCATED ON THE PATHFINDER#1 LOCATION NEAR THE NEATED SEPARATOR.								
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:	09/09/2024		Annual Brhd Completed?		Yes				
Last Brhd Test Results	Initial Surf Csg Pressure:		0		Fluid Type: NONE				
	End Surf Csg Pressure:		0						
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains	Pass	Culverts	Pass			
Gradient Terraces	Pass	Drains	Pass			
Waddles	Pass	Waddles	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass	Check Dams	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300767	INSP. PHOTOS	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6979858">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6979858</a>