

**Storm Water Management and Erosion control**  
**Location Name: QB Energy KRK 7-1 (A7E) Pad**  
**Location #: 323941**



**Location Overview: Location is within High  
Priority/Density/Black Bear Habitat areas.**

**Section/Township/Range: 7 7S92W**

**Storm water Management and Erosion control**  
**Location Name: QB Energy KRK 7-1 (A7E) Pad**  
**Location #: 323941**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

# Storm water Management and Erosion control

Location Name: QB Energy KRK 7-1 (A7E) Pad

Location #: 323941



Photo # 8015 Failure to minimize surface disturbance

Photo # 8016 Failure to minimize surface disturbance

## Storm water Management and Erosion control

Location Name: QB Energy KRK 7-1 (A7E) Pad

Location #: 323941



Photo # 8017 Failure to minimize surface disturbance



Photo # 8018 Failure to minimize surface disturbance

## Storm water Management and Erosion control

Location Name: QB Energy KRK 7-1 (A7E) Pad

Location #: 323941



Photo # 8019 Failure to minimize surface disturbance

Photo # 8020 Failure to minimize surface disturbance

## Storm water Management and Erosion control

Location Name: QB Energy KRK 7-1 (A7E) Pad

Location #: 323941



Photo # 8021 Failure to minimize surface disturbance

Photo # 8022 Failure to minimize surface disturbance

## Storm water Management and Erosion control

Location Name: QB Energy KRK 7-1 (A7E) Pad

Location #: 323941



Photo # 8023 Failure to minimize surface disturbance



Photo # 8024 Failure to minimize surface disturbance

**Storm water Management and Erosion control**  
**Location Name: QB Energy KRK 7-1 (A7E) Pad**  
**Location #: 323941**



**Photo # 8025 Failure to minimize surface disturbance**

**Photo # 8026 Failure to minimize surface disturbance**

## Storm water Management and Erosion control

Location Name: QB Energy KRK 7-1 (A7E) Pad

Location #: 323941



Photo # 8027 Failure to minimize surface disturbance



Photo # 8028 Failure to minimize surface disturbance