

Interim Reclamation and Stormwater Inspection

Date: 03/25/2025

Operator: PADCO LLC - 24500

Location ID: 317233

Inspection Document #: 718700227

Washington County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Fassler #6
Location ID: 317233



Photos 1 & 2. Taken from the northeast (Photo 1; left) and southeast (Photo 2; right) portions of the location. Guy lines anchors do not appear to be properly marked (e.g. bright colored marker not less than four (4) feet in height).

Inspection Photos
Location Name: Fassler #6
Location ID: 317233



Photos 3 & 4. Taken from the southwest (Photo 3; left) and northwest (Photo 4; right) portions of the location. Guy lines anchors do not appear to be properly marked (e.g. bright colored marker not less than four (4) feet in height).

Inspection Photos
Location Name: Fassler #6
Location ID: 317233



Photos 5 & 6. Tank labels/NFPA placards are not legible at day tanks (Photo 5; left) and wildlife exclusion device requires maintenance and/or replacement (Photo 6; right).

Inspection Photos
Location Name: Fassler #6
Location ID: 317233



Photos 7 & 8. Erosion degradation and unstabilized soils observed along the access road to the well location.

Inspection Photos
Location Name: Fassler #6
Location ID: 317233



Photos 9 & 10. Erosion degradation and unstabilized soils observed along the access road to the well location.