

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2025

Submitted Date:

03/28/2025

Document Number:

718700227

FIELD INSPECTION FORM

Loc ID 317233 Inspector Name: Edwardson, Dylan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 24500
 Name of Operator: PADCO LLC
 Address: 16508 ARMINTA STREET
 City: VAN NUYS State: CA Zip: 91406

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BROTHERTON, ANDREA		abrotherton@136elcamino.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237330	WELL	PR	09/01/2020	OW	121-09831	FASSLER 6	RI
317233	LOCATION	AC			-	FASSLER-62N53W 32NENE	RI

General Comment:

[This is an Interim Reclamation and Stormwater Inspection for Location ID 317233.](#)

Location

Overall Good:

Signs/Marker:

Type			
Comment:	Tank labels/NFPA placards near wellhead day tanks are not legible (e.g. peeling, faded, cracked, etc).		
	Install sign to comply with Rule 605.g.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

			corrective date
Type: Other	#		
Comment:	Previous FIR (doc #708200244) documented that day tanks near wellhead did not have any wildlife exclusion devices observed. During this inspection, it appears that wildlife exclusion devices have been installed since the previous inspection, however, one portion of the netting requires maintenance and/or replacement as it appears torn/inadequate. Refer to attached inspection photos.		
	Install or repair wildlife protection equipment per Rule 902.b.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Previous FIR (doc #708200244) documented that guy line anchors did not appear to be properly marked (e.g. bright marker not less than four (4) feet in height). During this inspection, it does not appear that that this corrective action has been resolved as the guy line anchors do not comply with Rule 1003.a. Refer to attached inspection photos.		
Corrective Action:	Install proper guy line markers per Rule 1003.a.	Date:	04/11/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 237330 Type: WELL API Number: 121-09831 Status: PR Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 317233 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. During this inspection, erosion degradation and unstabilized soils were observed along the access road leading to the well location. Refer to attached inspection photos.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 04/11/2025

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718700253	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6981714