

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2025

Submitted Date:

03/28/2025

Document Number:

707603773

**FIELD INSPECTION FORM**

Loc ID 305251 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275985	WELL	TA	03/30/2022	OW	123-22712	WARDLAW 35-25	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Plugging Operations: Re-entry; Cement-surface.  
Battery: Abandoned.  
Abandoned Battery SE corner GPS coordinates: 40.446350 / -104.522330  
Well GPS coordinates: 40.445788 / -104.521990

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 275985 Type: WELL API Number: 123-22712 Status: TA Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Axis Energy Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 939'-0' Cement Volume (sx): 308 sxs

Good Return During Job: \_\_\_\_\_ Cement Type: Class "G" Neat 15.8#

Comment: 2025/03/27:  
 Plugging Operations: Re-entry; Cementing; Cement-surface.  
 2025/03/27: JSA attached as photo to this report.

Workover Contractor: Axi Energy Services Rig #712.  
 Cement Contractor: Axis Energy Services.

HSM IWP VAC SURF  
 FLOW CHECK = NO FLOW  
 LD COLLARS FROM DERRICK  
 TIH 28 JNTS + 24' OF SUBS EOT 939'  
 R/U CEMENTERS BK CIRC  
 P/308 SX G TO SURF  
 LD TBG  
 NDBOP & BAG  
 CLEAN TANKS R/O PUMP & TANKS RDMO

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Workover**

Comment: 2025/03/27:  
 Plugging Operations: Re-entry; Cementing; Cement-surface.  
 2025/03/27: JSA attached as photo to this report.

Workover Contractor: Axis Energy Services Rig #712.  
 Cement Contractor: Axis Energy Services.

Reference:  
 Form 6N on file. Notice of Intent to Abandon date: 11/01/2021. Approved.  
 Form 42 on file. Notice of MIRU. Start Date: 03/18/2025. Approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On THU 03/27/2025 at approximately 09:43 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: WARDLAW-66N64W/35SENW                      Location ID: 305251                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this Field Inspection Report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Plugging Operations: Re-entry; Cement-surface.                      Battery: Abandoned.                      Abandoned Battery SE corner GPS coordinates: 40.446350 / -104.522330                      Well GPS coordinates: 40.445788 / -104.521990</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	03/28/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603774	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6982959">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6982959</a>