

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2025

Submitted Date:

03/24/2025

Document Number:

710500464**FIELD INSPECTION FORM**Loc ID 321117 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 61650Name of Operator: MURFIN DRILLING COMPANY INCAddress: 250 N WATER ST STE 300City: WICHITA State: KS Zip: 67202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Goodrich, Christina		cgoodrich@murfininc.com	Murfin Inspections
Serna, Abe		abe.serna@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206084	WELL	TA	12/02/2011	OW	009-06500	S.E. CAMPO UNIT 605	EI
321117	LOCATION	AC			-	S.E. CAMPO UNIT- 635S46W 1NENW	EI

General Comment:[This is an Environmental Inspection for the S E CAMPO UNIT # 605, API # 05-009-06500 well location and Rem # 37143](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel road through pasture			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign at wellhead			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	At the time of inspection, unused equipment was observed on location.			
Corrective Action:	Comply with Rule 606			Date: 04/22/2025
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:	At the time of inspection, stained soils observed running from the wellhead west off location coming to a stop in an area previously undisturbed by oil and gas activity			
Corrective Action:	Report spill or release of E&P waste or produced fluids, contact ECMC EPS staff per Rule 912.b.			Date: 03/25/2025
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Fencing around ancillary equipment			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Temporary fencing installed at wellhead excavation			
Corrective Action:				Date:
Equipment:				
Type: Flow Line	# 1			corrective date
Comment:	At the time of inspection, a flowline riser observed at the wellhead. Comply with Rule 1105 for flowline decommissioning			
Corrective Action:				Date:

<u>Venting:</u>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	206084	Type:	WELL	API Number:	009-06500	Status:	TA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	321117	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment:	<p>At the time of inspection, spoil pile from wellhead excavation was stored on location on a tarp without berms. Evidence of soil migration from stormwater impacts were present</p> <p>Per Rule 913.b.(5).B.iv. Operators will properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.</p>			
Corrective Action:	Operator shall properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil in accordance with Rule 913.b.(5).B.iv.			Date: 04/08/2025

Spill/Remediation:

Comment:	<p>Remediation project # 37143 is ongoing. At the time of inspection, impacted soils observed within the wellhead excavation. Per Form 6s Document # 404039247, wellhead cut and capped date of 12/09/2024. Operator did not report Spill or Release discovered during facility closure operations in the wellhead excavation in accordance with Rule 913.f.. Operator shall provide all analytical data and information collected at the time the wellhead was cut and capped.</p>		
Corrective Action:	Report spill or release of E&P waste or produced fluids, contact ECMC EPS staff per Rule 912.b.		Date: 03/25/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
Wellhead cut and capped on 12/09/2024 per Form 6s Document # 404039247	sanchezcc	03/24/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404138470	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6971657
710500465	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6971650