

Final Reclamation and Stormwater Inspection

March 17, 2025

Operator: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 319707

Well Name: DUMLER #2-A

Inspection Document #: 718600398

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DUMLER #2-A
Location ID: 319707



Photo 1. Looking northwest across entrance of access road. This spot has lower vegetation compared to surrounding area, with some bare soil.



Photo 2. Looking north down former access road. vegetation establishment is low on the road with non-uniform coverage. There is very little desirable vegetation establishment.



Inspection Photos
Location Name: DUMLER #2-A
Location ID: 319707



Photo 3. Looking north across the well location. Vegetation on well location appears to consist of weedy species such as Tansy and Blue Mustard, Kochia, Russian thistle, as well as List C noxious weed cheatgrass. Reference area vegetation is also poor but mustard family weeds are not as prevalent.



Photo 4. Looking east from wellbore. See photo 3 comments.



Inspection Photos
Location Name: DUMLER #2-A
Location ID: 319707



Photo 5. Looking south from wellbore. See photo 3 comments.



Photo 6. Looking west from wellbore. List B noxious weed scotch thistle is present on location.



Inspection Photos
Location Name: DUMLER #2-A
Location ID: 319707



Photo 7. Picture taken on west side of location. Scotch thistle on location



Photo 8. Reference vegetation to the west of location. Vegetation is relatively poor, primarily weedy plants and cheatgrass. Some native forbs.

