

Final Reclamation and Stormwater Inspection

March 25, 2025

Operator: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 320109

Well Name: ANDERSON #4

Inspection Document #: 718600441

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON #4
Location ID: 320109



Photo 1. Looking south down former access road. A large amount of list C noxious weed Downy Brome is present on access road. Desirable perennial vegetation has established on the access road and appears to be progressing towards 80% of reference area coverage.



Photo 2. Looking southwest across the well location. All oil and gas equipment has been removed. Densely covered in Downy Brome. Desirable vegetation is present throughout the site and appears to be progressing towards 80% vegetation coverage.



Inspection Photos
Location Name: ANDERSON #4
Location ID: 320109



Photo 3. Looking looking north from wellbore across location.
See photo 2 comments.



Photo 4. Looking east from wellbore. See photo 2 comments.



Inspection Photos
Location Name: ANDERSON #4
Location ID: 320109




Photo 5. Looking southwest across the flowline junction/ Spill area associated with this wells flowline. Vegetation is primarily list C noxious weed Downy Brome. The reference vegetation near the road has a much higher level of Downy Brome.



Photo 6. Looking southeast across flowline junction area. A sign marked gas pipeline. No other oil and gas equipment remains.

Inspection Photos
Location Name: ANDERSON #4
Location ID: 320109



Photo 7. Reference vegetation to the east of well location.