

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2025

Submitted Date:

03/31/2025

Document Number:

707603785

FIELD INSPECTION FORM

Loc ID 327512 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 1099 18TH STREET SUITE 1500
 City: DENVER State: CO Zip: 80202

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246993	WELL	TA	10/01/2019	OW	123-14790	STATE A36-9	TA

General Comment:

This is a WELL inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location ID (302425, 310494, 310631, 327512).
 (Well(s): 4: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
 A.) Field Inspection Report doc. #707603779 and/or Location ID #302425 for TA Well(s) info.
 B.) Field Inspection Report doc. #707603781 and/or Location ID #310494 for TA Well(s) info.
 C.) Field Inspection Report doc. #707603783 and/or Location ID #310631 for TA Well(s) info.
 D.) Field Inspection Report doc. #707603785 and/or Location ID #327512 for TA Well(s) info.
 E.) Field Inspection Report doc. #707603787 and/or Facility ID #302425 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	CORRECTIVE GUIDANCE Item(s): OOSLAT tag NOT posted at well. *Post OOSLAT tag at well. See photo #1.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	CORRECTIVE GUIDANCE Item(s): Overgrown vegetation at wellsite. *Remove, manage, & control overgrown vegetation around wellsite. See photo #1.		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS

	CENTRALIZED BATTERY		40.442688,-104.498935
Comment:	Centralized Battery serves 4 Location ID (302425, 310494, 310631, 327512). (Well(s): 4: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).		
Corrective Action:			Date:
Paint			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Maintenance
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 246993 Type: WELL API Number: 123-14790 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted at well.
OOSLAT applied at separator.
CECMC records last production: 11/2016.

Form 4 on file. TA date: 05/01/2019. Approved.
DH-Balanced plug.
Form 21-MIT on file. MIT date: 05/02/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 06/05/2020. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 02/02/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 03/27/2025 at approximately 11:08 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: STATE-66N64W/36NESE Location ID: 327512 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>CORRECTIVE GUIDANCE Item(s): 1.) Overgrown vegetation at wellsite. *Remove, manage, & control overgrown vegetation around wellsite. See "Good Housekeeping" section on page 2 of this report. 2.) OOSLAT tag NOT posted at well. *Post OOSLAT tag at well. See "Signs/Marker" section on page 2 of this report. See photo #1.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	03/31/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603786	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6984464