

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2025

Submitted Date:

03/28/2025

Document Number:

715202000**FIELD INSPECTION FORM**Loc ID 337558 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286795	WELL	PR	06/01/2007	GW	125-10341	WELP FAMILY FARMS 32-13	PR

General Comment:

SE Compliance Specialist Brian Welsh conducted an audit and routine field inspection of the well location and equipment

Location				
Lease Road:				
Type	Access			
comment:	Trail through farm ground			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign by unit			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Stuffing box had a leak and theres stained soil around the wellhead			
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.			Date: 04/25/2025
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Metal panels around unit and wellhead			
Corrective Action:				Date:
Equipment:				
Type: Pump Jack	# 1			corrective date
Comment:	Churchill unit			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Electric panel			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric motor			
Corrective Action:				Date:
Venting:				
Yes/No				

Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	286795	Type:	WELL	API Number:	125-10341	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Welp Family Farms 32-13 & 42-13) 1450' ESE of wellhead on W side of CR AA								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715202031	pumping unit	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6984654