

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2025

Submitted Date:

03/25/2025

Document Number:

707801497

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 416979 _____ Ramsey, Scott _____ 2A Doc Num: _____
Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 24 Number of Comments
 6 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416984	WELL	PR	03/22/2011	GW	045-19420	GGU MILLER FED 34B-32-691	PR
416985	WELL	PR	05/05/2011	GW	045-19421	GGU MILLER FED 33B-32-691	PR
416987	WELL	PR	03/22/2011	GW	045-19422	GGU MILLER FED 33A-32-691	PR
416988	WELL	PR	05/10/2011	GW	045-19423	GGU MILLER FED 33C-32-691	PR
416989	WELL	PR	05/10/2011	GW	045-19424	GGU MILLER 23B-32-691	PR
416990	WELL	PR	04/15/2011	GW	045-19425	GGU MILLER 24B-32-691	PR
416991	WELL	PR	04/15/2011	GW	045-19426	GGU MILLER 24A-32-691	PR
416992	WELL	PR	03/19/2015	GW	045-19427	GGU MILLER 24D-32-691	PR
416993	WELL	PR	03/23/2011	GW	045-19428	GGU MILLER FED 34C-32-691	PR
416994	WELL	PR	05/05/2011	GW	045-19429	GGU MILLER 24C-32-691	PR
416995	WELL	PR	05/05/2011	GW	045-19430	GGU MILLER 23C-32-691	PR
416996	WELL	PR	03/22/2011	GW	045-19431	GGU MILLER FED 34D-32-691	PR
416997	WELL	PR	03/22/2011	GW	045-19432	GGU MILLER FED 34A-32-691	PR

General Comment:

CECMC Inspection Report Summary

On Monday 3/24/2025, I, Inspector Scott Ramsey, conducted a routine inspection/audit at TEP GGU Miller MDP 6, at Location # 416979 in Garfield county Colorado. Shaun Kellerby was also on the inspections/audits with myself.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

We were escorted by lead pumper through locked gate and he also followed us around locations.

During this inspection the following compliance issues were observed:

1. Access road rock check dams are in need maintained.
2. Chemical tank containment is leaking, possibly chemical staining because pumps for chemical are also leaking. Stained soils around chemical containment.
3. Unused poly piping around location.
4. Random debris (B/H caps)
5. Open rat hole
6. Some tank labels are illegible.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Some tank labels are illegible.		
Corrective Action:	Provide proper labeling	Date:	04/25/2025
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Open rat hole at well head.		
Corrective Action:	Eliminate possibility of wildlife or personnel from falling into open holes.	Date:	04/04/2025
Type	DEBRIS		
Comment:	Random debris (B/H caps)		
Corrective Action:	Remove debris	Date:	04/04/2025
Type	STORAGE OF SUPL		
Comment:	Unused poly piping around location.		
Corrective Action:	Remove poly piping	Date:	05/02/2025
Type	OTHER		
Comment:	Chemical tank containment is leaking, possibly chemical staining because pumps for chemical are also leaking. Stained soils around chemical containment.		
Corrective Action:	Repair or replace secondary containment and Contact environmental for remediation of soils.	Date:	03/27/2025

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

Equipment:

			corrective date
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Not metered		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 13		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 13		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	416984	Type:	WELL	API Number:	045-19420	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	416985	Type:	WELL	API Number:	045-19421	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	416987	Type:	WELL	API Number:	045-19422	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	416988	Type:	WELL	API Number:	045-19423	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	416989	Type:	WELL	API Number:	045-19424	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	416990	Type:	WELL	API Number:	045-19425	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	416991	Type:	WELL	API Number:	045-19426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	416992	Type:	WELL	API Number:	045-19427	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 416993 Type: WELL API Number: 045-19428 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 416994 Type: WELL API Number: 045-19429 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 416995 Type: WELL API Number: 045-19430 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 416996 Type: WELL API Number: 045-19431 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 416997 Type: WELL API Number: 045-19432 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
Ditches						
Berms						
Ditches						
		Ditches				

Comment: [1. Access road rock check dams are in need maintained.](#)

Corrective Action: [Install, maintain or repair required BMPs](#)

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404140656	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974118
707801502	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974098