

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2025

Submitted Date:

04/01/2025

Document Number:

697011256

FIELD INSPECTION FORMLoc ID 310797 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297128	WELL	TA	05/01/2017	OW	123-26988	STONE RIDGE 24-15	WK

General Comment:

This is a well plugging audit.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	#		
Comment:	Rig, pump, work tanks and support equipment are grounded.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	297128	Type:	WELL	API Number:	123-26988	Status:	TA	Insp. Status:	WK
Cement									
Cement Contractor									
Contractor Name: Duco					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range):					Cement Volume (sx): 100 sxs				
Good Return During Job: YES					Cement Type: Class G Neat 15.8#				
<div>Comment: ND WH, NU BOPE, pressure test BOPE, POOH with tbg, hold safety meeting, MIRU SureFire e-line, RIH with CIBP #2 and set @ 3994' KB, POOH with setting tool, RIH with dumpbailer and spot 2 sxs of cement slurry on top of CIBP, POOH with dumpbailer, RIH with CIBP #3 and set @ 2239' KB, POOH with setting tool, RDMO e-line, TIH with tbg to 2239' KB, monitor wellbore, hold safety meeting, MIRU Duco cementers, establish circulation, pump 10 bbls fresh water spacer, mix and pump 10 sxs Class G Neat 15.8 ppg cement slurry (2.0 bbls total), displace tbg with 8.0 bbls of fresh water, RD cementers, lay down tbg to 922' KB, RU cementers, mix and pump 90 sxs Class G Neat 15.8 ppg cement slurry (18.4 bbls total) with cement returned to work tank, RD cementers, lay down remaining tbg, ND BOPE, top off cement to surface, NU WH, SIW, RDMO.</div>									
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Seeding	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697011257	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6986557