

Construction and Stormwater Inspection

April 1, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 486605

Well Name: ACACIA/13-17

Inspection Document #: 718600462

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ACACIA/13-17
Location ID: 486605



Photo 1. Sign and 2A posted near entrance of access road.



Photo 2. Looking east down access road. A track out mat is present on the outboard lane. Culvert under access road has inlet protection.



Inspection Photos
Location Name: ACACIA/13-17
Location ID: 486605



Photo 3. Riprap behind track out pad is full of sediment



Photo 4. Picture taken at northeast corner sediment trap. Outflow BMP are in place. A small amount of erosion is beginning to form under the culvert.



Inspection Photos
Location Name: ACACIA/13-17
Location ID: 486605



Photo 5. Looking south down the east side of location. Ditch appears stabilized.



Photo 6. Looking west between the southern topsoil stockpile and pad. Area appears stabilized with vegetation germination.



Inspection Photos
Location Name: ACACIA/13-17
Location ID: 486605



Photo 7. Picture taken at sediment trap at southwest corner of location. It does not appear that sediment is leaving the location.



Photo 8. Looking west along the southern edge of location. Southern topsoil stockpile appears to be stabilized with germination of vegetation.

Inspection Photos
Location Name: ACACIA/13-17
Location ID: 486605



Photo 9. Looking north between the pad and production facilities. Slope appears to have been stabilized and seeded with evidence of germination.



Photo 10. Triangular shaped topsoil stockpile on the west side of location. Stockpile appears to have been stabilized with crimped straw.



Inspection Photos
Location Name: ACACIA/13-17
Location ID: 486605



Photo 11. Looking at the northwest corner of the triangular topsoil stockpile towards the production facility. It appears that equipment has been driving over the corner of the topsoil stockpile.



Photo 12. Looking north down the west side of the location.



Inspection Photos
Location Name: ACACIA/13-17
Location ID: 486605



Photo 13. Looking northeast down the west side of the location. The ditch and berm have been removed for access out the west side of location. A culvert is not present and the road is muddy over the ditch. A soil pile without erosion BMPs is present.



Photo 14. Looking south down the west side of the location. The ditch and berm have been removed. It does not appear that the ditch can convey water to the sediment trap.



Inspection Photos
Location Name: ACACIA/13-17
Location ID: 486605



Photo 15. Looking east down the north side of location. Outlets are reinforced and a sediment trap is present.



Photo 16. Looking east down north side of location. Ditch is present and appears to be stabilized.