

Final Reclamation and Stormwater Inspection

Date: 04/01/2025

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - 8960

Location ID: 428278

Inspection Document #: 718700266

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Antelope M-31
Location ID: 428278



Photos 1 & 2. Taken from the northwestern portion of the location. Photos illustrate that the disturbance areas do not appear to be progressing towards reclamation standards and regulations with evidence of bare/unstabilized soils and undesirable vegetation.

Inspection Photos
Location Name: Antelope M-31
Location ID: 428278



Photos 3 & 4. Taken from the northern/center of the location. Photos illustrate that the disturbance areas do not appear to be progressing towards reclamation standards and regulations with evidence of bare/unstabilized soils and undesirable vegetation.

Inspection Photos
Location Name: Antelope M-31
Location ID: 428278



Photos 5 & 6. Taken near the southern/center portion of the location. Photo illustrates a portion of the disturbance area that appears to be experiencing wind erosion due to unstabilized soils.

Inspection Photos
Location Name: Antelope M-31
Location ID: 428278



Photos 7 & 8. Taken from the southeastern portion of the location. Photos illustrate that the disturbance areas do not appear to be progressing towards reclamation standards and regulations with evidence of bare/unstabilized soils and undesirable vegetation.

Inspection Photos
Location Name: Antelope M-31
Location ID: 428278



Photos 9 & 10. Taken near the former access point, or northeastern portion of the location. Photo illustrates the presence of undesirable vegetation (CO List C Noxious Weed-cheatgrass) throughout.

Inspection Photos
Location Name: Antelope M-31
Location ID: 428278



Photos 11 & 12. Examples of undesirable vegetation observed throughout the reclaimed disturbance areas; cheatgrass (left) and russian thistle (right).