

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2025

Submitted Date:

04/03/2025

Document Number:

718700266

FIELD INSPECTION FORM

Loc ID: 428278 Inspector Name: Edwardson, Dylan On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421218	WELL	PA	07/07/2022	OW	123-32853	Antelope G-31	RI
421219	WELL	PA	07/07/2022	OW	123-32854	Antelope I-31	RI
428264	WELL	PA	07/07/2022	OW	123-35293	Antelope R-31	RI
428266	WELL	PA	10/17/2022	OW	123-35295	Antelope N-31	RI
428278	LOCATION	CL			-	Antelope M-31	RI
428281	WELL	PA	07/07/2022	OW	123-35303	Antelope H-31	RI
428292	WELL	PA	07/07/2022	OW	123-35306	Antelope M-31	RI
428294	WELL	PA	07/07/2022	OW	123-35307	Antelope L-31	RI

General Comment:

This is a Final Reclamation Inspection at a plugged and abandoned multi-well location and the associated tank battery. The last well (API 123-35295) was plugged and abandoned 10/17/2022.

Inspected Facilities				
Facility ID: <u>421218</u>	Type: <u>WELL</u>	API Number: <u>123-32853</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>421219</u>	Type: <u>WELL</u>	API Number: <u>123-32854</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>428264</u>	Type: <u>WELL</u>	API Number: <u>123-35293</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>428266</u>	Type: <u>WELL</u>	API Number: <u>123-35295</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>428278</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>428281</u>	Type: <u>WELL</u>	API Number: <u>123-35303</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>428292</u>	Type: <u>WELL</u>	API Number: <u>123-35306</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>428294</u>	Type: <u>WELL</u>	API Number: <u>123-35307</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured Pass

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present **Fail** Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: This location does not comply with Rule 1004. During this inspection, it was observed that the location appears to have been contoured and graded to reflect adjacent topography. The former tank battery and well locations consist primarily of unstabilized/bare soils and debris from undesirable vegetation (russian thistle/tumbleweeds). A Colorado List C Noxious Weed (cheatgrass) was also observed to be growing throughout the disturbance areas and will require management. Additional reclamation activities are required to comply with Rule 1004.

Corrective Action:	Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.	Date _____
Overall Final Reclamation	Fail	Well Release on Active Location <input type="checkbox"/>
		Multi-Well Location <input checked="" type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718700273	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989892