

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2025

Submitted Date:

04/06/2025

Document Number:

713400806

FIELD INSPECTION FORM

Loc ID 334183 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

25 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ENERGY, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
306	WELL	PR	03/02/2010	GW	045-15478	PRATHER/LATHAM 3-31A	PR
307	WELL	PR	04/14/2010	GW	045-15479	MANESS 3-31D	PR
308	WELL	PR	03/01/2010	GW	045-15480	MANESS 3-31B	PR
309	WELL	PR	01/01/2025	GW	045-15481	MANESS 3-31C	PR
310	WELL	PR	04/01/2010	GW	045-15482	PRATHER/LATHAM 3-21B	PR
311	WELL	PR	03/31/2010	GW	045-15483	MANESS 3-21C	PR
312	WELL	PR	04/13/2010	GW	045-15484	MANESS 3-21D	PR
313	WELL	PR	03/10/2010	GW	045-15485	PRATHER/LATHAM 3-21A	PR

General Comment:

[CECMC Inspection/Audit Report Summary](#)

On 04/2/2025 at approximately 12:39 hours, Compliance Inspector Dusty Popejoy conducted a follow up inspection/audit at QB ENERGY PRATHER/LATHAM-68S96W/3NWNE (3B 896 PAD) at Location ID #334183 in Garfield County, Colorado.

Please refer to inspection/audit 713400707 conducted on 02/10/2025, previous corrective actions have been completed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

While there, I observed normal production operations.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Automation - Hog panels		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	No form of pressure monitoring equipment. Bradenhead valves are accessible		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	300 BBLs	STEEL AST		,
Comment:	3 of 5 Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	306	Type:	WELL	API Number: 045-15478	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	307	Type:	WELL	API Number: 045-15479	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	308	Type:	WELL	API Number: 045-15480	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	309	Type:	WELL	API Number: 045-15481	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	310	Type:	WELL	API Number: 045-15482	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	311	Type:	WELL	API Number: 045-15483	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	312	Type:	WELL	API Number: 045-15484	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						
Facility ID:	313	Type:	WELL	API Number: 045-15485	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12						

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Berms				
		Compaction				
Ditches						
Sediment Traps						
Gravel						Sparse
Berms						
		Culverts				
		Gravel				Sparse
Compaction						Light Compaction

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400807	Inspection-Audit Photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6992306