

Caerus Piceance LLC – QB Energy Corporation LLC
Figure Four Unit-64S98W 1SWSW
Location ID: 335790



Erosion and sediment migration



Stormwater BMP not maintained

Caerus Piceance LLC – QB Energy Corporation LLC
Figure Four Unit-64S98W 1SWSW
Location ID: 335790



Unmarked anchor




Debris

Caerus Piceance LLC – QB Energy Corporation LLC
Figure Four Unit-64S98W 1SWSW
Location ID: 335790



Debris



Debris

Caerus Piceance LLC – QB Energy Corporation LLC
Figure Four Unit-64S98W 1SWSW
Location ID: 335790




Unmarked anchor



Debris

Caerus Piceance LLC – QB Energy Corporation LLC
Figure Four Unit-64S98W 1SWSW
Location ID: 335790



Debris



Well sign not displayed

Caerus Piceance LLC – QB Energy Corporation LLC
Figure Four Unit-64S98W 1SWSW
Location ID: 335790



Unused equipment



Unmarked anchors

Caerus Piceance LLC – QB Energy Corporation LLC
Figure Four Unit-64S98W 1SWSW
Location ID: 335790



Location from North entrance



Location from South corner