

**Operator: BONANZA CREEK ENERGY OPERATING CO.**

**Location Name: Pronghorn 31-9 Pad**

**Loc ID: 306037**

**Inspection: 718700177**



**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**

**CA:** This location does not comply with Rule 1004. Previous FIR (doc #713900049) documented that the access road and well location did not appear to have been reclaimed (e.g. contoured or graded). Operator submitted FIRR (doc #403620207) stating that the corrective action was completed and the location was mowed, recontoured and reseeded. During this inspection, it was observed that the access road and location appeared to have been previously reseeded, however, the location does not appear to have been contoured or graded to reflect the adjacent topography or pre-disturbance conditions. Additional reclamation activities (e.g. contouring, grading, etc) is required. Refer to attached inspection photos. Comply with Rule 1004. Contour/grade the entire location and reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

**CA Resolution:** Operator has completed the recontouring of this location to match surrounding topography and seeding, in order to comply with Rule 1004.