

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2025

Submitted Date:

04/08/2025

Document Number:

717300283

**FIELD INSPECTION FORM**

Loc ID 331631 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10633  
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
 Address: 555 17TH STREET SUITE 3700  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264084	WELL	SI	08/02/2024	OW	123-21008	CONNER 41-4	PA
318375	LOCATION	AC			-	CONNER-61N66W 4NENE	EG

**General Comment:**

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photos uploaded](#)

**Inspected Facilities**

Facility ID: 264084 Type: WELL API Number: 123-21008 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 318375 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Well is plugged and abandoned (Conner 41-4); ECMC form 42 notice of start of plugging operations doc #403895156 received 08/20/2024. No flowlines/ risers observed at PA wells or facility/ battery area. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed. Remediation work on location is in progress.	maclarej	04/08/2025
As outlined on COGCC form 19 spill report Doc #404152809 received on 04/04/2025: While conducting facility decommissioning activities at Crestone's Conner 41-4 wellhead historical impacts were discovered. The impacted soil will be removed and hauled for disposal. Lease operators are coached to conduct routine AVO inspections at all oil and gas locations.	maclarej	04/08/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300285	PA well location; view S	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6994660">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6994660</a>
717300286	Signage	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6994661">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6994661</a>
717300287	Facility decommissioned; OOS DCP Riser	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6994662">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6994662</a>