

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2025

Submitted Date:

04/02/2025

Document Number:

708906164

**FIELD INSPECTION FORM**Loc ID 323783 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 3 GREENWAY PLAZA STE 1360

City: HOUSTON State: TX Zip: 77046

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

27 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mustang		nwelch@venatorresources.com	
Longworth, Mike		mike.longworth@state.co.us	
Heil, John		john.heil@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210798	WELL	PR	07/01/2024	GW	045-06556	MEAD 23-44-6S-94W	PR

**General Comment:****CECMC Inspection/Audit Report Summary**

On 03/31/2025 at approximately 14:11 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection/audit at MUSTANG RESOURCES LLC MEAD 23-44-6S-94W Pad.

Location # 323783 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to Bald Eagle Roost site & NSO Habitat area.

Location is approximately 240 yards from Beaver Creek & approximately 575 yards from the Colorado River.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Housekeeping - Trash on the ground near compressor with a CA date of 04/09/2025
2. Fencing - Barbed wire fence needs maintenance/wildlife hazard with a CA date of 04/09/2025
3. Equipment - PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules with a CA date of 04/09/2025
4. Stormwater/Material Handling & Spill Prevention - Tank near dehy containing an unknown fluid with a CA date of 05/17/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Compressor engine oil tank		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/888-291-8588	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash bags laying on the ground near compressor, additionally there appears to be a small amount of staining near the trash bags		
Corrective Action:	Operators will properly dispose of all trash, rubbish, and other waste materials as non-hazardous/non-E&P solid waste, pursuant to Rule 906.c.  All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.	Date:	04/09/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence Barbed wire fence needs maintenance/wildlife hazard		
Corrective Action:	Comply with CECMC wildlife rules	Date:	04/09/2025
<b>Equipment:</b>			corrective date
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter for the MEAD 23-44-6S-94W well		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Well is not on plunger lift		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Inlet scrubber/slug catcher		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	3 marked deadman & 1 improperly marked deadman - please refer to photo log All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	It appears operator had not previously submitted a FORM 12 for the gas gathering system, however FORM 12 was submitted by operator on 03/31/2025 Gas Gathering Pipeline System - FORM 12 document # 404147138 Status "IN PROCESS"		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Fire extinguisher		
Corrective Action:		Date:	
Type: Compressor	# 1		

Comment:	It appears operator had not previously submitted a FORM 12 for the compressor station on location, however FORM 12 was submitted by operator on 03/31/2025				
	Gas Compressor Station - FORM 12 document # 404146526				
	Status unknown, document does not appear to be in the location file but was located in a laserfiche weblink search				
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	Compressor master meter				
Corrective Action:				Date:	
Type: Other	# 3				
Comment:	PRV vent line on compressor does not comply with CECMC pressure safety device rules				
	PRV & rupture disc vent lines on dehy do not comply with CECMC pressure safety device rules				
Corrective Action:	Comply with CECMC pressure safety device rules			Date:	04/09/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	Compressor engine oil
Other (Capacity)	500 gal
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	OTHER	STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					
					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		

Comment:	Separate containment		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected Facilities									
Facility ID:	210798	Type:	WELL	API Number:	045-06556	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams						
		Compaction				Small amount of light compaction
Compaction						Small amount of light compaction
Berms						
Gravel						Sparse to none in areas
		Gravel				Sparse to none in areas
				Material Handling And Spill Prevention	Fail	Tank near dehy 2/3 to 3/4 full of unknown fluid

Comment: 1. Tank near dehy approximately 2/3 to 3/4 full of an unknown fluid/not in compliance with CECMC rules (additionally tank lacks any BMP's)

Corrective Action: Provide proof of contents, along with SDS information & comply with all applicable CECMC rules or remove from location

Date: 05/17/2025

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Housekeeping, Fencing, Equipment & Stormwater for corrective actions & also refer to Equipment for comments.	smelserw	04/02/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404151121	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6988149">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6988149</a>
708906166	Inspection/Audit 708906164 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6988143">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6988143</a>
708906168	Inspection/Audit 708906164 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6988144">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6988144</a>