

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2025

Submitted Date:

04/02/2025

Document Number:

710500471

FIELD INSPECTION FORMLoc ID 308220 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Serna, Abe		abe.serna@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Ward, Giena		gward@ogrisop.com	
Baca, Dave		dbaca@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264234	WELL	PR	05/03/2010	CBM	071-07679	GOLDEN EAGLE 22-13	EI
292695	PIT	AC			-	GOLDEN EAGLE 22-13	EI
308220	LOCATION	AC			-	GOLDEN EAGLE-633S67W 22SWSW	EI

General Comment:

This is an Environmental Inspection for the Golden Eagle 22-13 well location, Facility ID 308220 and Pit Facility 292695, located in Las Animas County, Colorado.

All previous comments in Field Inspection Report # 698707245 shall apply

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Well Placard located on Meter House		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency Contact number is illegible.		
Corrective Action:	Update emergency contact to comply with Rule 605.g.	Date:	05/02/2025

Good Housekeeping:

Type	DEBRIS		
Comment:	At the time of inspection, debris from the well location observed off the east edge of location.		
Corrective Action:	Cleanup debris, manage location in accordance with Rule 606	Date:	04/09/2025
Type	UNUSED EQUIPMENT		
Comment:	The Engine Skid on location is not operational and appears to be unused equipment. Per Inspection photos from Field inspection # 698707245, 350 Engine, Missing Carburetor Operator shall manage unused equipment in accordance with Rule 606		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	At the time of inspection, Pit Facility ID 292695 is not in use and appears to be unused equipment.		
Corrective Action:	Operator shall submit a Form 27-i for decommission of Pit Facility ID 292695 in accordance with Rule 911 and 913.	Date:	05/05/2025

Overall Good: ☐

Spills:			
Type	Area	Volume	
Produced Water	Flow Line		
Comment:	At the time of inspection, there was evidence of water flow from the Pit Dump Line. Soils below the Dump Line show signs of impacts from water flow with damp soils extending into the pit excavation. There is an accumulation of water in the pit bottom. At the time of inspection, the well did not have a drive head and did not appear to be capable of producing water. The Operator shall investigate and provide information for the potential release of produced water to Pit Facility ID 292695		
Corrective Action:	Report spill or release of E&P waste or produced fluids, remove free fluids and contact ECMC EPS staff per Rule 912.b. for directives		Date: 04/03/2025

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
--------	--	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	264234	Type:	WELL	API Number:	071-07679	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	292695	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	308220	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of inspection, evidence of stormwater erosion was identified on the SE corner of the production pit.

Corrective Action: Operator shall implement BMPs in accordance with Rule 1002.f.(3).A.iv.

Date: 05/02/2025

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Percolation Lined: NO Pit ID: 292695 Lat: 37.152900 Long: -104.880700

Reference Point: _____ Other: _____ Length: 61 Width: 45

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Pit permitted as an unlined production pit for Facility ID 308220

Pit Dimensions 61' x 45' x 8' average depth +/-.

Corrective Action

Date:

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date:

Monitoring:	Monitoring Type	Comment
	Other	T-Post set in NW corner of pit

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404151040	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6988014
710500474	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6988005