

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2025

Submitted Date:

04/02/2025

Document Number:

715501489

**FIELD INSPECTION FORM**

Loc ID: 312968  
Inspector Name: Burchett, Kirby  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 18 Number of Comments  
 3 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 10407  
 Name of Operator: ANTLER ENERGY LLC  
 Address: PO BOX 104  
 City: BAGGS State: WY Zip: 82321

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Hoak, Thomas	(720) 594-8372	thomas.hoak@state.co.us	
Evans, Clay	(307) 380-7616	clay@antler-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100421	PIT		09/23/1999		-	POWDER WASH FED. 28-3	
100424	PIT		09/23/1999		-	POWDER WASH FED. 28-3	
223072	WELL	PR	08/26/1981	GW	081-06434	POWDER WASH FEDERAL 28-3	PR

**General Comment:**

[ECMC Inspection Report Summary](#)

On Tuesday, 04/01/2025, Inspector Kirby Burchett, conducted a follow up field inspection at Antler Energy LLC on the Powder Wash Federal 28-3 well, Location #312968, in Moffat County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715501198 on 1/28/25 and 4 previous inspections dating back to 6/6/23. Operator submitted FIRR #404136507 on 3/20/25 indicating 12 of 12 Corrective Actions have been resolved. The following corrective actions have not been resolved and original due dates remain:

1. Unused equipment.
2. Production pit containing liquid open to wildlife.
3. Stained soils.

Refer to Inspection Photos for observed compliance issues.

While there during normal operations no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Required information illegible from a distance		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	307-380-7616		Date:
Corrective Action:			

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Open top pit inside tank battery with insufficient wildlife protection.		
Corrective Action:	Install or repair wildlife protection equipment.	Date:	06/17/2023
Type	UNUSED EQUIPMENT		
Comment:	Out of Service equipment on location. No gas sales reported. Equipment is not in use.		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	07/05/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	Pump Jack		
Comment:	Stained soil from equipment leak.		
Corrective Action:	Clean up, remove and properly dispose of oily waste and stained soils.	Date:	06/22/2023

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:	Livestock and barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Lube oil tank inside containment		

Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:	All equipment not hooked up or out of service will be removed from location.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	All equipment not hooked up or out of service will be removed from location.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	All equipment not hooked up or out of service will be removed from location.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	All equipment not hooked up or out of service will be removed from location.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				
				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 100421 Type: PIT API Number: - Status: \_\_\_\_\_ Insp. Status: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 100424 Type: PIT API Number: - Status: \_\_\_\_\_ Insp. Status: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 223072 Type: WELL API Number: 081-06434 Status: PR Insp. Status: PR

**Producing Well**

Comment: [January 2025 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: \_\_\_\_\_ Pit ID: 100421 Lat: 40.889639 Long: -108.298966  
 Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**  
 Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_  
 Comment: None  
 Corrective Action:  Date: \_\_\_\_\_

**Fencing:**  
 Fencing Type: Livestock Fencing Condition: Inadequate  
 Comment:   
 Corrective Action:  Date: \_\_\_\_\_

**Netting:**  
 Netting Type: Mesh Netting Condition: Holes  
 Comment:   
 Corrective Action:  Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_  
 Comment:   
 Corrective Action:  Date: \_\_\_\_\_

Type: \_\_\_\_\_ Lined: \_\_\_\_\_ Pit ID: 100424 Lat: 40.889639 Long: -108.298966  
 Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**  
 Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_  
 Comment: None  
 Corrective Action:  Date: \_\_\_\_\_

**Fencing:**  
 Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_  
 Comment: None  
 Corrective Action:  Date: \_\_\_\_\_

**Netting:**

Netting Type: <u>Mesh</u>	Netting Condition: <u>Sagging into pit contents</u>	
Comment:	<input style="width: 100%;" type="text"/>	
Corrective Action:	<input style="width: 100%;" type="text"/>	
Date:	<input style="width: 100%;" type="text"/>	
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:	<input style="width: 100%;" type="text"/>	
Corrective Action:	<input style="width: 100%;" type="text"/>	
Date:	<input style="width: 100%;" type="text"/>	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404150951	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6987798">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6987798</a>
715501490	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6987790">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6987790</a>