

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2025

Submitted Date:

04/03/2025

Document Number:

718700266

**FIELD INSPECTION FORM**Loc ID 428278 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421218	WELL	PA	07/07/2022	OW	123-32853	Antelope G-31	RI
421219	WELL	PA	07/07/2022	OW	123-32854	Antelope I-31	RI
428264	WELL	PA	07/07/2022	OW	123-35293	Antelope R-31	RI
428266	WELL	PA	10/17/2022	OW	123-35295	Antelope N-31	RI
428278	LOCATION	CL			-	Antelope M-31	RI
428281	WELL	PA	07/07/2022	OW	123-35303	Antelope H-31	RI
428292	WELL	PA	07/07/2022	OW	123-35306	Antelope M-31	RI
428294	WELL	PA	07/07/2022	OW	123-35307	Antelope L-31	RI

**General Comment:**

This is a Final Reclamation Inspection at a plugged and abandoned multi-well location and the associated tank battery. The last well (API 123-35295) was plugged and abandoned 10/17/2022.

**Inspected Facilities**

Facility ID:	421218	Type:	WELL	API Number:	123-32853	Status:	PA	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	421219	Type:	WELL	API Number:	123-32854	Status:	PA	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	428264	Type:	WELL	API Number:	123-35293	Status:	PA	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	428266	Type:	WELL	API Number:	123-35295	Status:	PA	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	428278	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI
--------------	--------	-------	----------	-------------	---	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	428281	Type:	WELL	API Number:	123-35303	Status:	PA	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	428292	Type:	WELL	API Number:	123-35306	Status:	PA	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	428294	Type:	WELL	API Number:	123-35307	Status:	PA	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured Pass

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% Fail Cropland: perennial forage \_\_\_\_\_

Weeds present Fail Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: This location does not comply with Rule 1004. During this inspection, it was observed that the location appears to have been contoured and graded to reflect adjacent topography. The former tank battery and well locations consist primarily of unstabilized/bare soils and debris from undesirable vegetation (russian thistle/tumbleweeds). A Colorado List C Noxious Weed (cheatgrass) was also observed to be growing throughout the disturbance areas and will require management. Additional reclamation activities are required to comply with Rule 1004.

Corrective Action:	Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.	Date _____
Overall Final Reclamation	<b>Fail</b>	Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input checked="" type="checkbox"/>

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404152842	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989900">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989900</a>
718700273	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989892">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989892</a>