

# Interim Reclamation and Stormwater Inspection

Date: 04/07/2025

Operator: IMPERTO RESOURCES LLC - 10690

Location ID: 317278

Inspection Document #: 718700275

Washington County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Chandler 2-15  
Location ID: 317278



**Photos 1 & 2.** Undesirable vegetation previously documented appears to have been managed for. Operator shall continue to monitor and manage the location for undesirable vegetation.



Inspection Photos  
Location Name: Chandler 2-15  
Location ID: 317278



**Photos 3 & 4.** Maintenance advised on access points/production areas.



Inspection Photos  
Location Name: Chandler 2-15  
Location ID: 317278



**Photos 5 & 6.** Photo 5 (left) illustrates that a perimeter ditch has been installed along the western portion of the location. Photo 6 (right) illustrates that erosion degradation previously observed near the separator does not appear to have been repaired or stabilized.



Inspection Photos  
Location Name: Chandler 2-15  
Location ID: 317278



April 7, 2025  
131° SE  
ECMC




April 7, 2025  
127° SE  
ECMC

**Photos 7 & 8.** Photos illustrate that perimeter stormwater controls appear to be properly functioning. Photo 8 (right) illustrates weedy debris on pit walls.



Inspection Photos  
Location Name: Chandler 2-15  
Location ID: 317278



**Photos 9 & 10.** Evidence of erosion degradation observed at the pit walls.



Inspection Photos  
Location Name: Chandler 2-15  
Location ID: 317278



April 7, 2025  
300° NW  
ECMC




April 7, 2025  
151° SE  
ECMC

**Photos 11 & 12.** Visible hydrocarbons observed on the surface of skim pit with visible sheen evident.





Inspection Photos  
Location Name: Chandler 2-15  
Location ID: 317278



**Photos 13 & 14.** Erosion degradation previously observed near the well location does not appear to have been repaired or stabilized to prevent reoccurrence.