

Interim Reclamation and Stormwater Inspection

Date: 04/07/2025

Operator: TIMKA RESOURCES LTD - 88370

Location ID: 317129

Inspection Document #: 718700279

Washington County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Theurer Farms 22-28
Location ID: 317129



Photos 1 & 2. Northwest guyline anchor (Photo 1; left) requires reinstallation. Wildlife netting at secondary containment (Photo 2; right) near well location requires maintenance.

Inspection Photos
Location Name: Theurer Farms 22-28
Location ID: 317129



April 7, 2025
36° NE
ECMC



April 7, 2025
312° NW
ECMC

Photos 3 & 4. Visible leaks observed at the wellhead and pump jack unit.

Inspection Photos
Location Name: Theurer Farms 22-28
Location ID: 317129



Photos 5 & 6. Tank labels/NFPA placards are not legible (e.g. peeling, faded, cracked, etc) and require replacement.

Inspection Photos
Location Name: Theurer Farms 22-28
Location ID: 317129



Photos 7 & 8. Southwest portion of pit. Pit berms do not appear to be properly stabilized with evidence of erosion degradation and sediment transport occurring. Additional stormwater control measures are required.

Inspection Photos
Location Name: Theurer Farms 22-28
Location ID: 317129



Photos 9 & 10. Western portion of pit. Pit berms do not appear to be properly stabilized with evidence of erosion degradation and sediment transport occurring. Additional stormwater control measures are required.

Inspection Photos
Location Name: Theurer Farms 22-28
Location ID: 317129



Photos 11 & 12. Northern portion of pit. Pit berms do not appear to be properly stabilized with evidence of erosion degradation and sediment transport occurring. Additional stormwater control measures are required.

Inspection Photos
Location Name: Theurer Farms 22-28
Location ID: 317129



Photos 13 & 14. Northeastern portion of pit. Pit berms do not appear to be properly stabilized with evidence of erosion degradation and sediment transport occurring. Additional stormwater control measures are required.

Inspection Photos
Location Name: Theurer Farms 22-28
Location ID: 317129



Photos 15 & 16. Southeastern portion of pit. Pit berms do not appear to be properly stabilized with evidence of erosion degradation and sediment transport occurring. Additional stormwater control measures are required.