

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2025

Submitted Date:

04/04/2025

Document Number:

713400799

FIELD INSPECTION FORMLoc ID 324042 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
ENERGY, QB		ecmc.inspections@qb-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211562	WELL	SI	05/01/2024	GW	045-07322	HYRUP 12-11	PA

General Comment:**CECMC Inspection/Audit Report Summary**

On 4/3/2025 at approximately 12:05 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at QB ENERGY HYRUP-68S96W/12NWNW (Hyrup 12-11) at Location ID #324042 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Inspected Facilities - Unable to locate FORM 6 Subsequent Report of Abandonment with a CA date of 04/19/2025

This well was located in Williams compressor facility.

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location				
Lease Road:				
Type	Access			
comment:	Access			
Corrective ActionL			Date:	
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 211562 Type: WELL API Number: 045-07322 Status: SI Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Well has been plugged and abandoned. Unable to locate FORM 6 Subsequent Report of Abandonment.Corrective Action: Comply with CECMC rules

Date: 04/19/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Please refer to Inspected Facilities for corrective action.	popejoyd	04/04/2025
This well was located in Williams compressor facility.		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404153730	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6990937
713400801	Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6990932