

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2025

Submitted Date:

04/11/2025

Document Number:

698707355

FIELD INSPECTION FORM

Loc ID 308857 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Baca, Dave	719-846-4066	dbaca@ogrisop.com	
Giena Zeches	719-220-4041	gzeches@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283707	WELL	SI	05/01/2019	CBM	071-08731	GOLDEN EAGLE 22-05X	SI

General Comment:

P&A Operation

Location

Overall Good:

Signs/Marker:

	Type OTHER		
Comment:	Well sign on meter house		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 283707 Type: WELL API Number: 071-08731 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: Ogris Operating Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): 161 Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 1775 Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: Rig Crew rigged up cement truck & water truck,mixed 23 sks @ 15.8 Pumped 23 sks from 1775'-1625'.
 Rig Crew tripped out of hole to 915' mixed 138 sks hoohed up and pumped from 915'-0 surface.
 Once out the hole topped off to surface
 Job Complete.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
P&A Operation	sernaa	04/11/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698707356	Photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7001595