

# Inspection Photos

Loc: 321831

Operator: **P O & G OPERATING LLC**

Inspection Date: 4/10/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



**Photo 1.** Facing southeast toward the tank battery.



Inspection Photos



**Photo 2.** Facing east toward the well site and pumpjack.



## Inspection Photos



**Photo 3.** There are oil stained soils at the base of the pumpjack that need to be cleaned up and properly disposed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

## Inspection Photos



**Photo 4.** There is oily fluid in this secondary containment of the chemical barrel with no wildlife protections. This needs to be netted to prevent wildlife entry.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

## Inspection Photos



**Photo 5.** There is stained soils at the wellhead that need to be cleaned up and properly disposed. Also there is unused equipment stored in the upper right of the photo which needs to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

## Inspection Photos



**Photo 6.** The tank battery sign has fallen over and the tank labels are faded.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

## Inspection Photos



**Photo 7.** Facing northeast at the tank battery facility.



Inspection Photos



**Photo 8.** View of inside the shed shows oil stained soils and improper spill containment.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

Inspection Photos



**Photo 9.** Facing northeast past the shed. There was a spill that occurred which leaked out both inside and outside of secondary containment in this area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

## Inspection Photos



**Photo 10.** Facing southeast inside the tank battery. The is stained soil from a leak that occurred. The red arrow points to 4.5 ft. shovel for scale.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

## Inspection Photos



**Photo 11.** There is also oil stained soils that went outside of containment at the north side of the location. The shovel was placed by the stained soils for scale.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

Inspection Photos



**Photo 12.** Facing southwest at the north side of the location where the spill occurred outside of containment..



## Inspection Photos



**Photo 13.** There is a pile of gravelly sand material stored at the northeast corner of the location. There is stained material incorporated into the pile. E&P waste must be stored with containment and liner.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025

Inspection Photos



**Photo 14.** Northeast corner of the location facing southwest. Red arrow points to blackened stains soil at the pile shown previous photo.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 321831 | Date: 4/10/2025