

Inspection Photos

API: 017-07112

Operator: **P O & G OPERATING LLC**

Inspection Date: 4/10/2025

County: Cheyenne



Inspection Photos



Photo 1. Facing southwest at the beginning of the access road. There is vehicle traffic going around the cattleguard causing widening of the road and unnecessary surface disturbance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 2. Facing south along the access road. The access road is rutted and not maintained in this area. Vehicle are widening the road at this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07112 | Date: 4/10/2025

Inspection Photos



Photo 3. The culvert along the access road near the wellsite has washed out and needs to be repaired.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07112 | Date: 4/10/2025

Inspection Photos



Photo 4. Facing south toward the wellsite.



Inspection Photos



Photo 5. The pumpjack has been removed and there is hardened oil stained soil shown at red arrow. Also the fence panels need to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07112 | Date: 4/10/2025

Inspection Photos



Photo 6. Facing west from the wellsite. There appears to have been a previous leak that occurred downhill from the wellhead which has impacted crop growth.



Inspection Photos



Photo 7. Facing east at the edge of the deficient crop growth. This is approximately 150 ft. downhill from the wellhead.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07112 | Date: 4/10/2025