

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013




Photo # 9782 From entrance to location

Photo # 9783 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013



Photo # 9784 Location



Photo # 9785 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013



Photo # 9786 Location



Photo # 9787 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013



Photo # 9788 Location



Photo # 9789 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013



Photo # 9790 Open ended load line



Photo # 9791 Unused flowline at separators lacks lockout tagout (OOSLAT)

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013



**Photo # 9792 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 9793 PRV vent line does not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013



Photo # 9794 Wellhead cellar lacks wildlife egress



Photo # 9795 Wellhead cellar lacks wildlife egress

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013



**Photo # 9796 Secondary containment metal tank ring rusted /damaged & needs maintenance**



**Photo # 9797 Secondary containment metal tank ring rusted /damaged & needs maintenance**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK C Pad

Location ID: 336013



**Photo # 9798 Secondary containment metal tank ring rusted /damaged & needs maintenance**



**Photo # 9799 Secondary containment metal tank ring rusted /damaged & needs maintenance**