

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad

Location ID: 324013



Photo # 468 From entrance to location



Photo # 469 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad

Location ID: 324013



Photo # 470 Location



Photo # 471 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad

Location ID: 324013



Photo # 474 Location



Photo # 475 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad

Location ID: 324013



Photo # 476 Tank is disconnected & not in use/unused equipment



Photo # 477 Tank is disconnected & not in use/unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad

Location ID: 324013



Photo # 478 Tank is disconnected & not in use/unused equipment



Photo # 479 Tank is disconnected & not in use/unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad

Location ID: 324013



Photo # 480 Staining on top of tank & down the side of tank that indicates the tank may lack integrity.



Photo # 481 Staining down side of tank

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad

Location ID: 324013



Photo # 482 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules



Photo # 483 PRV & rupture disc vent lines do not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 10-30 D Pad

Location ID: 324013



Photo # 484 Debris



Photo # 485 Debris