

Interim Reclamation and Stormwater Inspection

April 9, 2025

Operator: TYLER ROCKIES EXPLORATION LTD - 41550

Location ID: 420871

Location Name: Peoria Tank Battery/

Inspection Document #: 718600476

Arapahoe County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 1. Looking south across west side of the location. Stormwater BMPs (berm) are present around what appears to be land application sites.



Photo 2. Looking east along berm towards tank battery.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 3. Inside the berm there are large areas of bare soil and vegetation is primarily undesirable weedy vegetation.



Photo 4. Looking north across the location. List B noxious weed Scotch Thistle is present throughout the location. Large areas of bare soil are present within the location disturbance.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 5. Looking north long the back of the tank battery.



Photo 6. Southern two crude oil tanks and sign.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 7. Northern produced water tank and sign.



Photo 8. Equipment in front of produced water tank. Two buckets containing oily fluid are present.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 9. Looking northwest at the separator shed. Barrel secondary containment does not have a wildlife exclusion device installed.



Photo 10. Inside shed. Chemicals and equipment are being stored inside the separator shed.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 11. Looking south across tank battery location near eastern potential land application field.



Photo 12. Pipe from produced water tank to evaporation pond is capped off.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 13. Looking north across evaporation pond. Channel erosion is present around the entire interior of the pond. Standing water is present in pond at the time of inspection.



Photo 14. Looking east long north side of pond. Heavy erosion is present on the outside of the berm and sediment is being transported off location by stormwater.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 15. Looking south down east side of pond. See photo 14 comments.



Photo 16. Looking west down south side of pond. See photo 14 comments.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 17. Looking southwest across pond towards former skim pit. Equipment remains in pond (pipes, wood material).



Photo 18. Looking east across inside of pond. See photo 17 comments.



Inspection Photos
Location Name: Peoria Tank Battery/
Location ID: 420871



Photo 19. Google earth aerial imagery from 06/2024. Illustrating land treatment areas (green arrows) and area within location disturbance with large areas of bare ground and list B noxious weed scotch thistle (red circle).