

**Operator: CRESTONE PEAK RESOURCES OPERATING LLC**

**Location Name: PURITAN-62N68W 34SWSE**

**Loc ID: 331935**

**Inspection: 718600260**



**Exhibit A**



**Exhibit B**



**Exhibit C**

**CA:** An in process Form 44 (Doc Id #402543661) submitted 12/01/2020 indicates the flowline between Puritan #34-34 (Loc ID #331935) and PURITAN/2N68W/34SESE (Loc ID #336413) was flushed and abandoned in place. There is a fenced open excavation at the wellbore. It appears the open excavation may be related to flowline abandonment. See attached photos. Continue to work with ECMC engineering staff for Form 44 approval. Fill and reclaim excavations according to Rule 1004.

**CA Resolution:** Operator has backfilled all holes on pad and addressed fencing in order to comply with Rule 1004.

**CA:** There is an open excavation on location. Fencing is not adequately installed to prevent entry. See attached photos. Comply with Rule 913.b.5.B.i. Fence excavations to prevent entry.

**CA Resolution:** Operator has addressed the issue, in order to comply with Rule 913.b.5.B.i.