

Inspection Photos

API: 017-06629

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 4/9/2025

County: Cheyenne



Inspection Photos



Photo 1. Facing west along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road has not been repaired.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06629 | Date: 4/9/2025

Inspection Photos



Photo 2. There are oily rags at shown at red arrow and stained soils. This must be removed and properly disposed. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing northwest at the werllsite. There are oil stained soils shown at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06629 | Date: 4/9/2025

Inspection Photos




Photo 4. Facing toward the wellhead. There are stained soils by the wellhead. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06629 | Date: 4/9/2025

Inspection Photos



Photo 5. Facing toward the pumpjack. The engine has been replaced with an electric motor. It is unknown if oil saturated soils were cleaned up due to sand previously spread over this area.



Inspection Photos



Photo 6. The labeling on the chemical barrel has been updated..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06629 | Date: 4/9/2025