




An excavation at a depth of approximately one foot below ground surface remains open at the location of Spill ID 489249.



Gray staining is visible outside of the separator berm.



Gray to black petroleum hydrocarbon staining is visible in situ in the area of Spill ID 489249. Petroleum hydrocarbon odor was observed when the stained soil was disturbed.




Petroleum hydrocarbon staining is visible on the surface of the separator above the impacted soil.




Petroleum hydrocarbon staining was visible at the edge of the excavation; petroleum hydrocarbon odor was observed.




Petroleum hydrocarbon staining is visible in a separate area beneath the west side of the separator; a strong petroleum hydrocarbon odor was observed when stained soil was disturbed.



Fiberglass tank label has faded and is no longer legible. A strong petroleum hydrocarbon odor was observed immediately downwind of the tanks. Livestock tracks are visible.



Livestock tracks are visible through the gap in the fencing, and on and within the tank containment berm. Separator and tank share fencing. Sign in foreground is not legible and does not reflect current Operator. Sign in background references Operator Emergency Contact Number is (303) 825-4822. Debris is visible.



Tufts of livestock fur are visible on the barbed wire stretched above a gap in the fencing.

