

Inspection Photos

Loc: 476137

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 4/9/2025

County: Cheyenne



Inspection Photos



Photo 1. Facing southeast toward the tank battery. The E&P waste from the previously observed spill has been placed on a plastic liner at the north side of the tank battery.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 2. Facing northeast toward the tank battery. The oil stained waste remains around the tanks. Some of the tanks were removed since the previous inspection.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 3. The previously observed that occurred near the heater treater. The surface and equipment was/is blackened from a hydrocarbon mist that occurred.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 4. Southeast corner of the location facing northwest toward the tank battery facility. The previous spill had overtopped this corner with visible impacts shown in the previous inspection photos on 1/28/25.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 5. It appears there was also a condensate leak that flowed from the shed at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 6. There are signs of a leak at the top of the fiberglass tank shown at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 7. Drone aerial photo facing northeast toward the tank battery facility.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 8. Drone aerial photo facing northwest toward the tank battery facility. The previous spill that occurred flowed to this southeast corner and overtopped the berm.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 9. Drone aerial photo facing down toward the south side of the tank battery. There is oily liquid shown on top of the tank at red arrow which need to be cleaned up and properly disposed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 4/9/2025

Inspection Photos



Photo 10. Drone aerial photo facing down toward the north side of the tank battery.



Inspection Photos



Photo 11. Drone aerial photo facing south toward the tank battery facility.

