

Inspection Photos

Loc: 381172

Operator: CITATION OIL & GAS CORP

Inspection Date: 4/9/2025

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the two track access road. There is an erosion channel along the road closer to the location that needs to be repaired.



Inspection Photos



Photo 2. Facing northeast at the location. The location has not been reclaimed and there are areas bare of vegetation. The cut slope can be seen at the red arrow.



Inspection Photos



Photo 3. Facing northwest at the location. This is the approximate area of the well and pumpjack. This area is mostly bare of vegetation which indicates possible soil impacts.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:381172 | Date: 4/9/2025

Inspection Photos



Photo 4. Further downhill to the northwest from the abandoned well the vegetation impacts are evident.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:381172 | Date: 4/9/2025

Inspection Photos



Photo 5. Facing back to the southwest. There is an erosion channel along this area and soils are bare of vegetation.



Inspection Photos



Photo 6. Facing south along the cut slope. The cut slope is approximately 2-3 ft. and needs to be resloped with topsoil and revegetated.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:381172 | Date: 4/9/2025

Inspection Photos



Photo 7. Facing south along the cut slope. The cut slope is approximately 2-3 ft. and needs to be resloped with topsoil and revegetated.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:381172 | Date: 4/9/2025

Inspection Photos



Photo 8. Facing northwest at the location.

