

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/10/2025

Submitted Date:

04/14/2025

Document Number:

715501518

FIELD INSPECTION FORM
 Loc ID 335602 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num:
Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

28 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287171	WELL	PR	09/29/2006	GW	103-10907	FEDERAL RGU 23-6-297D	PR
294122	WELL	PR	10/01/2010	GW	103-11151	FEDERAL RGU 432-6-297	PR
294123	WELL	SI	01/01/2025	GW	103-11152	FEDERAL RGU 522-6-297	PR
294125	WELL	PR	12/27/2007	GW	103-11154	FEDERAL RGU 433-6-297	PR
301864	WELL	PR	01/01/2025	CBM	103-11484	FEDERAL RGU 33-6-297R	PR
301865	WELL	PR	01/01/2023	GW	103-11485	FEDERAL RGU 312-6-297	PR
301866	WELL	PR	02/01/2023	GW	103-11486	FEDERAL RGU 413-6-297	PR
301867	WELL	SI	01/01/2025	GW	103-11487	FEDERAL RGU 513-6-297	PR
301868	WELL	SI	01/01/2025	GW	103-11488	FEDERAL RGU 322-6-297	SI
301869	WELL	PR	04/02/2021	GW	103-11489	FEDERAL RGU 523-6-297	PR

General Comment:

ECMC Inspection Report Summary

On Thursday, 04/10/2025, Inspector Kirby Burchett, conducted a follow up field inspection at TEP Rocky Mountain LLC on the Federal RGU 23-6-297 pad, Location #335602, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District, Wildlife Management Plan, and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #702502252 on 3/25/24. All Corrective Actions have been resolved.

While there during normal operations the following compliance issues were observed:

1. Unused equipment.
2. Open end tank valves.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment storage on location.		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	04/30/2025

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Corral panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Corral and fence panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Emission Control Device	# 6		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 4		
Comment:	Methanol tank and 3 chemical tanks not in use		
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:	3 Quad units. Existing wells.		
Corrective Action:			Date:
Type: Bradenhead	# 10		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 16		
Comment:	4 Quad units. Wells to be drilled.		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 19		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Air compressor and bulk tank. Pnematic controllers.		
Corrective Action:			Date:
Type: Gas Meter Run	# 10		
Comment:	Inside existing well separators		
Corrective Action:			Date:
Type: VRT	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 16		
Comment:	Inside future well separators		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:		Lined		
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	HEATED STEEL AST		,
Comment:		Open end tank valves.			
Corrective Action:		All load lines or tank valves that can be used as a load line will be capped or plugged.			Date: 04/21/2025

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:		Lined		
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate				
Comment: Lined					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment: Lined					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	8	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment: Lined					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID:	287171	Type:	WELL	API Number: 103-10907 Status: PR Insp. Status: PR
Producing Well				
Comment:	February 2025 Production Report			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	294122	Type:	WELL	API Number: 103-11151 Status: PR Insp. Status: PR
Producing Well				
Comment:	February 2025 Production Report			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	294123	Type:	WELL	API Number: 103-11152 Status: SI Insp. Status: PR
Producing Well				
Comment:	February 2025 Production Report			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	294125	Type:	WELL	API Number: 103-11154 Status: PR Insp. Status: PR
Producing Well				
Comment:	February 2025 Production Report			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301864	Type:	WELL	API Number: 103-11484 Status: PR Insp. Status: PR
Producing Well				
Comment:	February 2025 Production Report			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301865	Type:	WELL	API Number: 103-11485 Status: PR Insp. Status: PR
Producing Well				
Comment:	February 2025 Production Report			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301866	Type:	WELL	API Number: 103-11486 Status: PR Insp. Status: PR
Producing Well				
Comment:	February 2025 Production Report			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301867	Type:	WELL	API Number: 103-11487 Status: SI Insp. Status: PR
Producing Well				
Comment:	February 2025 Production Report			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Producing Well			
Comment:	February 2025 Production Report		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301868	Type:	WELL	API Number:	103-11488	Status:	SI	Insp. Status:	SI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder:
Comment:	February 2025 Production Report Shut In - November 2024		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	301869	Type:	WELL	API Number:	103-11489	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	February 2025 Production Report		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501520	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7004717