

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2025

Submitted Date:

04/08/2025

Document Number:

708906200

**FIELD INSPECTION FORM**Loc ID 335146 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: 401705291**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

30 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259720	WELL	PR	04/04/2001	GW	045-07773	CLOUGH RWF 344-18	PR
265376	WELL	PR	04/28/2003	CBM	045-09000	CLOUGH RWF 44-18	PR
273743	WELL	PR	04/24/2005	GW	045-10273	FEDERAL RWF 444-18	PR
273745	WELL	PR	04/20/2005	GW	045-10272	CLOUGH RWF 414-17	PR
286002	WELL	PR	08/02/2006	GW	045-12596	CLOUGH RWF 544-18	PR

**General Comment:****CECMC Inspection/Audit Report Summary**

On 04/08/2025 at approximately 12:33 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 Pad.  
Location # 335146 in Garfield County Colorado.  
Location is within High Priority/Density Habitat areas.  
Location is approximately 177 yards from a creek/drainage that contributes to the Colorado River.  
While there, I observed normal production operations.  
During this inspection/audit the following compliance issues were observed:

1. Housekeeping - Unused equipment on location with a CA date of 05/08/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	RWF 44-18, RWF 444-18 & RWF 344-18 wellhead signs cracking & peeling but still legible at this time - Please refer to photo log.			
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Chemical tank			
Corrective Action:				Date:
Type	OTHER			
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-9377			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	Chemical tank on location is disconnected & not in use/unused equipment			
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.			Date: 05/08/2025
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	TANK BATTERY			
Comment:	Hog panels			

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank Equipment is not in use/unused equipment - please refer to Housekeeping for CA		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	No form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent				
Comment: Centralized containment						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment: Tank equipped with telemetry						
Corrective Action:				Date:		
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent				
Comment: Centralized containment						
Corrective Action:				Date:		
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:				Date:		

Inspected Facilities									
Facility ID:	259720	Type:	WELL	API Number:	045-07773	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	265376	Type:	WELL	API Number:	045-09000	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273743	Type:	WELL	API Number:	045-10273	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	273745	Type:	WELL	API Number:	045-10272	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	286002	Type:	WELL	API Number:	045-12596	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams						
Waddles						
		Gravel				Sparse to none in sections
Sediment Traps						
Compaction						Light compaction in some areas
Gravel						Sparse to none in areas
		Compaction				
		Ditches				
Tracking Pad						Aggregate/gravel based VTC
Rip Rap						
Other						Hay bales
		Culverts				
				Material Handling And Spill Prevention		Chemical tank containment

Comment: Aggregate/gravel based VTC near entrance to location. Dimensions & details are as follows - approximately 75 ft long, 24 ft wide & varying depths from 1/2 - 2 inches, depth insufficient, gravel undersized, area does not appear to have been excavated & no class 2 geotextile fabric observed. VTC is compacted in some areas.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
Please refer to Housekeeping for corrective action & also refer to Signs/Marker for comments.	smelserw	04/08/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404157993	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995573">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995573</a>
708906201	Inspection/Audit 708906200 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995571">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995571</a>
708906202	Inspection/Audit 708906200 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995572">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6995572</a>