

Interim Reclamation and Stormwater Inspection

Date: 04/11/2025

Operator: TIMKA RESOURCES LTD - 88370

Location ID: 312211

Inspection Document #: 718700304

Logan County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photos 1 & 2. The former pit near the well location does not appear to be progressing towards Rule 1003 standards and regulations with evidence of bare/unstabilized soils and undesirable vegetation.

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photos 3 & 4. Trash and debris observed around the former pit.

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photos 5 & 6. Trash and debris observed around the former pit.

Location ID: 312211



Photos 7 & 8. Stained soil observed around the pump jack.

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photos 9 & 10. Stained soil observed around the pump jack (Photo 9; left) and guy line anchor needs to be reinstalled (Photo 10; right).

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photos 11 & 12. Tank labels are not adequate (Photo 11; left) and unused equipment west of tank battery (Photo 12; right).

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photos 13 & 14. NFPA placards or tank labels were not observed at equipment.

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photos 15 & 16. Evidence of erosion degradation and sediment transport observed around the pit at the tank battery facility.

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photos 17 & 18. Erosion degradation observed along the access road at the well location.

Inspection Photos
Location Name: Kirk Lynch 1
Location ID: 312211



Photo 19. Portions of the interim areas at the well location do not appear to be progressing towards Rule 1003 standards or regulations with bare/unstabilized soils evident.