

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2025

Submitted Date:

04/15/2025

Document Number:

715801079

**FIELD INSPECTION FORM**Loc ID 330898 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256279	WELL	SI	03/01/2024	GW	123-19839	HSR-MILLER FEDERAL 15-6A	WK

**General Comment:**[This is a wellsite file audit followed by a field inspection.](#)

Location				
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	DRILLING/RECOMP			
Comment:	adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**Facility ID: 256279 Type: WELL API Number: 123-19839 Status: SI Insp. Status: WK**BradenHead**Date of Last Brhd Test: 03/17/2025 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Plumbed to surface.Corrective Action: Date: **Workover**Comment: Ranger WO Rig RU over the well for P&A operations, Ranger Wireline on location RIH with a gauge ring.Corrective Action: Date: 

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment

User

Date

This Audit/Inspection is due to a form 42 MIRU doc # 404162842  
 Any corrective actions from previous Inspections that have not been addressed are still applicable  
 Weather: Clear  
 Temperature: 70\*  
 Location: Dry.

revasr

04/15/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801080	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7006371">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7006371</a>