

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2025

Submitted Date:

04/09/2025

Document Number:

700300794

FIELD INSPECTION FORM

Loc ID: 325310
Inspector Name: LABOWSKIE, STEVE
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31250
Name of Operator: FRITZ & DIGMAN INC
Address: PO BOX 70024
City: ALBUQUERQUE State: NM Zip: 87197-

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Flores, Marie		marie@walsheng.net	contractor for various operators in SW
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Digman, Bernie	575-640-1867	berniekdigman@gmail.com	
, Engineering		dnr_cogccengineering@state.co.us	
Digman, Rebecca	505-379-8689	rcdigman@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214538	WELL	SI	06/01/2023	OW	067-06141	DAKOTA FEE 1	PA

General Comment:

Routine post plugging inspection to confirm cut and cap, equipment/flowline removal and site conditions. This inspection does not address Form 27 compliance. Impacted material material from spill appears to have been removed. Cemet resiue/washout still present and should have been cleaned up, surface plug set in December

Wellhead flange has been cut off but casing is not capped. Continuous bubbling observed through standing fluid inside casing. Area around casing appears to be solidified cement and oil resdue that has come from well. Operator submitted Form 6 (s) doc# 4040876651 inaccurately reporting well had been capped.

Well is to be re-entered and replugged to assure that all fluids are isolated appropriately and potential to emit is eliminated. Form 6 Notice of Intent should be filed by 5/9/2025. It is expected that work is completed and reported by 7/9/2025.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: cementing residue not cleaned up, oily spill response boom material no longer in use, stored on site. Residual cement and oily material around casing.

Corrective Action: Clean up residual cement, spill materials and cemeten and oil around casing and monument.

Date: 04/23/2025

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type

Comment: battery fencing has been removed

Corrective Action:

Date:

Equipment:

corrective date

Type: Pump Jack # 0

Comment:

Corrective Action:

Date:

Type: Other # 0

Comment:

Corrective Action:

Date:

Type: Bradenhead # 0

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	0	300 BBLs	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: tank removed, berms still present				
Corrective Action: _____				Date: _____
Venting:				
Yes/No	YES			
Comment:	casing not capped, bubbling gas			
Corrective Action:	Re-plug well after obtaining an approved Form 6 to ensure no gas migration from wellbore			Date: <u>07/09/2025</u>
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities

Facility ID: 214538 Type: WELL API Number: 067-06141 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: Well not capped, bubbling gas and fluid observed between casing and cement, see attachewmnt section for uploaded videos

Cement residue/washout east of wellhead, oily spill containment material still on site, tank berms still porent. Tank, pumpjack and flowlines removed.

Well plugged Fail Pit mouse/rat holes, cellars backfilled In

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured In Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: <input type="text"/>	Date <input type="text"/>	
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Optical Gas Imaging Survey

Survey Type: _____

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Gusts _____ Speed: 3-10 (mph) Direction From: sw Weather: Clear Temperature: (F) _____

Assisting Staff: _____ Camera #: _____

Visible Smoke Referred to CDPHE

Times Surveyed _____ Equipment Surveyed _____

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Wellhead(s)

Comment:

Corrective Action: Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404158435	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996202
700300796	INSPECTION PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996162
700300797	VIDEO OF BUBBLING FLUID AND GAS @ CASING	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996163
700300798	OGI VIDEO OF CASING	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6996164