

Inspection Photos

API: 011-05055

Loc: 321208

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 4/10/2025

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 4/10/2025

Inspection Photos



Photo 2. Facing northwest toward the GAS PROCESSING PLANT and Wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 4/10/2025

Inspection Photos



Photo 3. Facing northwest toward the GAS PROCESSING PLANT and Wellsite. There is various supplies and debris scattered throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 4/10/2025

Inspection Photos



Photo 4. Facing southwest at the sheds and various equipment which are in disrepair. There is chemical barrels with no containment and various debris laying on the ground.



Inspection Photos



Photo 5. Facing northwest at the sheds and various equipment which are in disrepair. There is still oil stained soils from the barrel that leaked out shown at red arrow.



Inspection Photos



Photo 6&7. There are sheds in disrepair with large bird nests. Operator will need to consult with USFS and CPW regarding time restrictions and relocation of any migratory bird nests.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 4/10/2025

Inspection Photos



Photo 8. Facing northwest at the sheds and equipment which are in disrepair. There was an audible gas leak coming from this shed and separator shown at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 4/10/2025

Inspection Photos



Photo 9. Facing southeast at the west side of the location. This shed and fence are in disrepair with supplies have fallen out of the dilapidated shed.



Inspection Photos



Photo 10. There is panels, boards, and a blue barrel laying on the ground which has leaked out fluids onto the ground. There is also impacted soils shown at red arrow.



Inspection Photos



Photo 11. Facing northeast toward the well. The fence around the pumpjack is in disrepair and there is unused equipment stored near the well.



Inspection Photos



Photo 12. Facing southeast at the location. There are various unused equipment, wire, and debris stored on location that needs to be removed.



Inspection Photos



Photo 13. Facing west at the location. There is various unused equipment, supplies and tanks stored at the location that will need to be removed. The soils in this area are stained with hydrocarbon impacts from historic spill.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 4/10/2025

Inspection Photos



Photo 14. Facing east at the south side of the location. This open top tank remains with oily fluids.



Inspection Photos



Photo 15. Facing toward the open top tank which has oil condensate inside the tank. Netting has now been installed over the tank. There are still opening on the sides that are large enough for birds to get into the tank.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 4/10/2025

Inspection Photos



Photo 16. Facing northeast at the location. This tank was installed since the 8/7/24 inspection.



Inspection Photos



Photo 17. East side of the location facing north. There is a large tank at the east side which does not appear to be in use.



Inspection Photos



Photo 18. East side of the location facing west.



Inspection Photos



Photo 19. Drone aerial photo taken on 2/4/2025. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 20. Drone aerial photo taken on 2/4/2025. Facing southwest toward the GAS PROCESSING PLANT and Wellsite.

